


Modell: CRETA



(D) **Montageanleitung**

(NL) **Handleiding voor de montage**

(TR) **Montaj talimatı**

(F) **Notice de montage**

(CZ) **Montážní návod**

(HU) **Szerelési útmutató**

(GB) **Assembly instructions**











(PL) **Instrukcja montażu**





(RU) **Инструкция по монтажу**

(IT) **Istruzioni di montaggio**

























(SK) **Návod na montáž**


(RO) **Instrucțiuni de montaj**






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	1668	362	16	1	2/2
2	830	396	16	1	1/2
3	830	396	16	1	1/2
4	1668	358	16	1	2/2
5	976	358	16	1	1/1
6	978	93	16	1	1/2
7	788	358	16	1	2/2
8	788	358	16	1	2/2
9	1668	93	16	1	2/2
10a	804	344	3	1	2/2
10b	804	344	3	1	2/2
11	493	992	3	1	1/2
12	311	992	3	1	2/2
13	330	328	16	2	1/2
14	989	196	16	1	2/2
15	300	100	12	1	2/2
16	930	100	12	1	2/2
17	300	100	12	1	2/2
18	940	301	3	1	2/2
19	829	334	16	2	1/2
20	584	493	16	2	1/2





I



W1




x1

A6



x4

W2




x1

B1







ø8x35

x4




0,5h





II




M8

300mm

x2

I1





x10

G34




3,5x16


x4

 $a=b$ 

III



H23



H35-300mm


x1


G20




5x13

x4






IV



K5



x4

B1



ø8x35



x12

K1







ø15x12



x12












B1





K5		x10	B1		x4
F2		x4	K1		x4





F2



x4

G20



5x13

x6

K1



Ø15x12

x4


B1



Ø8x35


x8

K5






x6

H23



H35-300mm

x1



B1


K5

H23

G20




F2

K1






VII

D4 H=0
x4





VIII



D10 H=2
x4




IX





X




A1		W2	
ø7x50	x4		x1




XI




XII



G14
3,5x45 x3



XIII



XIV

S2



x26


G34






3,5x16


x42

I1




x6

 $a=b$ 



XV

P20




x6

G12





4x25


x6



P20

G12





XVI

S2





x8









G34






3,5x16


x8







XVII





XVIII



G34




3,5x16

x8

C10



Ø35



Z35PL

x4

XIX



G34




3,5x16

x8


C4


Ø35








x4


XX






XXI





XXII

17



ø18

x24

