




















X3



STEP 1




STEP 2

E3.5*35



6PCS





STEP 3

B



4PCS




The diagram illustrates the connection of the power cord to the power supply unit in three steps:



- Step 1:** The power cord's three-pronged plug is shown being inserted into the power input socket on the side of the power supply unit.
- Step 2:** The power cord is shown fully inserted into the power input socket.
- Step 3:** The power cord is shown being plugged into a wall outlet.

E

6PCS





STEP 5



X3

STEP 6



X3

STEP 7

G




G3

3SET

H



6PCS




STEP 8

C

3.5*14



6PCS




STEP 9

J





4PCS

K



15PCS



STEP 10

